Vehicle History Report - Accident Edition

SAMPLE REPORT - ANONYMIZED EXAMPLE

Xiaomi Auto

Xiaomi YU7 2025 model Xiaomi YU7 Rear-Wheel Drive Long-Range Pure Electric

VIN: Hidden in sample report

Engine identifier	Recorded registration date
Hidden in sample report	**2026-01-04**

01 / Key Vehicle Checks

Use the available records alongside an independent vehicle inspection. No record does not prove the vehicle is accident-free.

Total loss record	Water immersion record	Fire damage record	Theft and robbery record
Abnormal record indicated	No record indicated	No record indicated	No record indicated

02 / Important Vehicle Condition Notice

Frame record	Engine	Transmission
No record indicated	No record indicated	No record indicated

Airbags	Commercial operation record	Unsettled case
No record indicated	No record indicated	Abnormal record indicated

High-value vehicle damage record	Batch-entered record	Risk warning
Abnormal record indicated	No record indicated	Abnormal record indicated

03 / Historical Record Overview

Number of closed accidents for this vehicle	**0**
Number of closed accidents where this vehicle is the third-party vehicle	**2**
Number of open accidents for this vehicle (including accidents where this vehicle is the third-party vehicle)	**1**
Maximum historical loss amount	**Approximately CNY 184,000**
Number of historical loss locations	**0**
Number of historical accidents under compulsory traffic insurance	**1**
Number of historical accidents under commercial motor insurance	**2**

04 / Historical Loss Location Overview

Historical loss information comes from accident reports and does not necessarily reflect the vehicle's current condition. Use it only as a reference when assessing the actual vehicle.

No location flag

Recorded location flag

Front	✓
Right front	✓
Right middle	✓
Right rear	✓
Rear	✓
Left rear	✓
Left middle	✓
Left front	✓
Roof	✓
Underbody	✓



These are source-reported location flags, not a current inspection. No location flag does not mean accident-free. Review all claim and risk sections.

Generic vehicle illustration; not a photograph of this vehicle.

Record availability	**No records returned**

05 / Frame Repair Record

The following information is the result of an analysis of this vehicle's historical accident records and is for reference only; please refer to the actual vehicle condition.



Highlighted labels indicate repair locations explicitly identified in the source. Unmarked components are not proof of an undamaged vehicle.

Generic passenger-car illustration; labels identify the source's reference points.

Structural damage points: No records returned.
Structural repair records: No records returned.

06 / Reinforcement Part Repair Record

The following information is the result of an analysis of this vehicle's historical accident records and is for reference only; please refer to the actual vehicle condition.



Highlighted labels indicate repair locations explicitly identified in the source. Unmarked components are not proof of an undamaged vehicle.

Generic passenger-car illustration; labels identify the source's reference points.

Reinforcement damage points: No records returned.
Reinforcement repair records: No records returned.

07 / Commercial Operation Information Overview

Current owner type	**Individual**
Whether there has ever been a non-individual owner	**Yes**
Current vehicle usage type	**Non-commercial use (enterprise category)**
Whether there has ever been a commercial operation record	**No**
Number of owners * Calculated based on the number of license plates the vehicle has had	**1 owner**
Time since first registration	**Within 1 year**

08 / Vehicle Information

Vehicle brand	**Xiaomi Auto**
Vehicle model	**Xiaomi YU7 2025 model Xiaomi YU7 Rear-Wheel Drive Long-Range Pure Electric**
Engine number	**Hidden in sample report**
Vehicle displacement (ml)	**0**
Emission standard	**-**
Vehicle type	**Passenger vehicle with fewer than six seats**
Approved passenger capacity	**5**

09 / Vehicle Insurance History

Commercial motor insurance refers to the source's non-mandatory motor insurance category, not commercial vehicle use.

Compulsory traffic insurance currently in force	**Yes**
Whether compulsory traffic insurance has been continuously insured	**Yes**
Longest single lapse period for compulsory traffic insurance	**/**
Commercial motor insurance currently in force	**No**
Whether commercial motor insurance has been continuously insured	**Yes**
Longest single lapse period for commercial motor insurance	**/**
Vehicle and vessel tax paid-on-behalf status	**Yes**

10 / Closed Accidents for This Vehicle

Record availability	**No records returned**

11 / Closed Accidents Where This Vehicle Is the Third Party

Q3 2026 / Record 1

Claim period	**Q3 2026**
Insurance type	**Commercial motor insurance**
Claim status	**Closed**
Vehicle loss amount range (CNY)	**CNY 170,000 (inclusive) to CNY 200,000**
Recorded vehicle loss amount (CNY)	**184000**
Supplier loss ratio	**2**
Damage location	**Not available**
Record processing time	**2026-10-16T14:29:15.000+08:00**
Reason	**Not available**
Liability	**Full liability**
Third-party involvement	**Yes**

Repair method	Repair item	Quantity
Repair	**Constructive total loss**	**1**

Q3 2026 / Record 2

Claim period	**Q3 2026**
Insurance type	**Compulsory traffic insurance**
Claim status	**Closed**
Vehicle loss amount range (CNY)	**CNY 0 (inclusive) to CNY 1,000**
Recorded vehicle loss amount (CNY)	**500**
Supplier loss ratio	**0**
Damage location	**Not available**
Record processing time	**2026-10-16T14:29:15.000+08:00**
Reason	**Not available**
Liability	**Full liability**

11 / Closed Accidents Where This Vehicle Is the Third Party (continued)

Third-party involvement	**Yes**

Repair method	Repair item	Quantity
Repair	**Removal and installation: rear windshield glass**	**1**

12 / Open Accidents for This Vehicle

Q3 2026 / Record 1

Claim period	**Q3 2026**
Insurance type	**Commercial motor insurance**
Claim status	**Claim registered**
Vehicle loss amount range (CNY)	**CNY 0 (inclusive) to CNY 1,000**
Recorded vehicle loss amount (CNY)	**500**
Supplier loss ratio	**0**
Damage location	**Not available**
Record processing time	**2026-10-16T14:29:15.000+08:00**
Reason	**Not available**
Liability	**Full liability**
Third-party involvement	**No**

Repair method	Repair item	Quantity
Repair	**Removal and installation: rear windshield glass**	**1**

13 / ChinaCarVIN Vehicle Condition Reminder

Further inspection recommended	**Yes**
Source risk notice	**This vehicle may have an accident history involving water immersion, and the loss details are unclear; further inspection of the actual condition is recommended.**

14 / ChinaCarVIN Recall Reminder

Information	**No recall record was obtained for this vehicle.**

15 / Glossary

New vehicle purchase price

Refers to the price of a new vehicle of the same type as the purchased and insured vehicle at the place where the insurance contract is signed; the information is for reference only; please rely on the actual result.

First registration date:

Refers to the registration date at the vehicle management office, i.e., the date of first registration of the motor vehicle; replacing the vehicle registration document will not change the registration date.

Total loss

With reference to the definition standards of various insurance companies for total loss vehicles, when the vehicle's maximum historical loss amount / new vehicle guide price ≥ 50%, it is defined as total loss.

Water immersion

If the vehicle has had an accident case of the type flooding or water immersion, it is defined as water immersion.

Fire damage

If the vehicle has had an accident case of the type fire, explosion, or spontaneous combustion, it is defined as fire damage.

Theft and robbery

If the vehicle has had an accident of the type theft and robbery, it is defined as theft and robbery.

Loss amount

The right side of the accident occurrence time displays the vehicle loss amount caused by this accident, not the final case compensation amount. In addition, the compensation standards for different cases and the marking rules for accident records differ slightly; please rely on the actual inspection results. In data before 2015, the “vehicle loss amount” content may not conform to the display rules, resulting in it not being displayed.

Loss location

Only displays front, rear, top, left front, right front, left rear, rear, left middle, right middle, and bottom; others are not displayed. This field has minor errors; please rely on the actual inspection results. In data before 2015, the “loss location” content may not conform to the display rules, resulting in it not being displayed.

15 / Term Definitions (continued)

Commercial operation record:

If there is a commercial operation record in the vehicle's historical insurance information, it is displayed as “Abnormal”.

Batch-entered record:

After the vehicle has an accident, because the vehicle is damaged, information about replacement/repair of damaged parts is generated. When the operator uploads the information to the system for registration, if the upload method is batch upload, it is defined as having a “batch-entered” record; it is recommended to further inspect the actual vehicle condition.

More than half a year

Indicates that the vehicle has had lapse records, but the longest single lapse among the lapse records is longer than half a year. This information is for reference only; please rely on the actual inspection results.

Less than half a year

Indicates that the vehicle has had lapse records, but the longest single lapse among the lapse records is less than half a year. This information is for reference only; please rely on the actual inspection results.

16 / ChinaCarVIN Disclaimer

This report is compiled based on user-submitted information and legally sourced data from public, partner, and other sources available at the time of generation. It is for reference only for understanding vehicle history and transactions, does not constitute a guarantee of the truthfulness, accuracy, completeness of the information or vehicle condition, and is not professional advice of any kind. Data may be delayed, missing, or erroneous; please combine actual vehicle inspection, professional testing, and other independent verification before making prudent decisions. Relevant responsibilities shall be handled in accordance with legal provisions and the ChinaCarVIN User Service Agreement.

Questions about this report? Contact support@chinacarvin.com

17 / Additional Source Records

Vehicle use history / Record availability	**No records returned**
Insurance history / Record availability	**No records returned**
Exterior repair records / Record availability	**Not available**
Engine repair records / Record availability	**No records returned**
Transmission repair records / Record availability	**No records returned**
Seat belt repair records / Record availability	**No records returned**
Airbag repair records / Record availability	**No records returned**
Interior repair records / Record availability	**No records returned**
Other claim records / Record availability	**No records returned**
Additional vehicle information / Record availability	**Not available**

Risk observations

Last Date	**Not available**
Last Mileage	**Not available**
Major List	**No records returned**
Mileage List	**No records returned**

Additional vehicle status / Data availability	**Not available**
Recall Status / Record availability	**No**